

Safety Issue Type: Recalls

November 18 2022 NHTSA Campaign Number: 22V859000

Cracked Fuel Injector May Leak and Cause a Fire

A fuel leak in the presence of an ignition source such as hot engine or exhaust components, can increase the risk of a fire.

NHTSA Campaign Number 22V859000

Manufacturer Ford Motor Company

Components FUEL SYSTEM, GASOLINE

Potential Number of Units Affected 521778

Summary

Ford Motor Company (Ford) is recalling certain 2020-2023 Escape and 2021-2023 Bronco Sport vehicles equipped with 1.5L engines. A fuel injector may crack and leak fuel inside the engine compartment.

Remedy

Dealers will update the engine control software to include fuel injector leak detection and install a drain tube, free of charge. Owner notification letters are expected to be mailed December 19, 2022. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 22S73. This recall includes all vehicles previously recalled under 22V-191. Vehicles previously remedied under 22V-191 will need to have the new remedy performed.

Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Affected Products (7)

Vehicle

MAKE	MODEL	YEAR
FORD	BRONCO SPORT	2021-2023
FORD	ESCAPE	2020-2023

Associated Documents (2)

Recall Acknowledgement

RCAK-22V859-2054.pdf 645.551KB

<https://static.nhtsa.gov/odi/rcl/2022/RCAK-22V859-2054.pdf>

Defect Notice 573 Report

RCLRPT-22V859-3756.PDF 215.099KB

<https://static.nhtsa.gov/odi/rcl/2022/RCLRPT-22V859-3756.PDF>