



2200 Westland Rd Cheyenne WY US 82001 kengarfffordcheyenne.com

Customer Pay Invoice

\$3.15

RO# : 15049 | Tag# : 7346

Check-in: Mon Apr 22, 2024 | 12:06 PM

Vehicle	Service Advisor
2023 Ford Bronco Sport-CACTUS_GRAY	Andrew Braithwaite
3FMCR9B6XPRE33727	115452
License: 55.42	(307) 773 - 0341
7,992 Mi In / 7,992 Mi Out	
In Service: 01/24/2024	
Sold Date: 01/31/2024	

1. 40CS080	Customer States: Vehicle lost power while cruise control set at 75mph. Check engine and oil pressure lights illuminated. Turned off and checked oil dipstick for proper fluid level and it was good. Restarted and same condition, could only get up to 52 mph top speed on the way home. This is the second instance of this happening to this vehicle. The other time was around 3500 total miles on the vehicle.	Customer Pay	\$0.03
------------	---	--------------	--------

Job added by - on Mon Apr 22, 2024 | 12:06 PM

40CS080 -Check Engine or Warning Light	Labor	\$0.00
--	-------	--------

1. Verify concern. check engine light is on and vehicle is operating in de-rate mode. Test PCM with scan tool, memory P06AO P06DB P2682 P3401 P3403 U0284 P06DA P3402, K0EO P06AO P06DB P2682 P3401 P3403 U0284. Noted all codes are for outputs / actuators. Noted wiring diagram shows fuse 8 15 amp in BJB supplies power to affected components. Check fuse 8 in BJB and found fuse open. Install short indicator into fuse slot 8 in BJB and wiggle test wiring harness at rear of engine for turbo bypass valve and engine coolant bypass valve. R&I engine under shield and wiggle test wiring for A/C compressor, active grille shutter and variable oil pump. Wiggle test wire harness at front of engine for cylinder deactivation valve and noted short to ground on circuit CBK03 activated. Trace and locate short to ground on power circuit to wire harness rubbed thru on top of generator. IMPORTANT 0-3 Months in Service (MIS) Photos are Required on All Vehicle Lines. Submitted photos under report a vehicle concern on mobile PTS and received report number 202494613169. Cut open wire harness and cut out damaged area of circuit CBK03. splice in new circuit and rewrap harness. secure harness away from generator. Replace fuse 8 in BJB and clear codes.

Parts	\$0.03
-------	--------

DG9Z 14526J - CIRCUIT BREAKER ASY 1 - \$0.03

3. 00XKGI	Multi Point Inspection	Internal Pay	\$0.00
-----------	------------------------	--------------	--------

Job added by Sterling Shepherd on Mon Apr 22, 2024 | 12:06 PM

00XKGI -Multi Point Inspection	Labor	\$0.00
--------------------------------	-------	--------

1. Performed Complimentary Multi Point Inspection